











M. D. Erminger

Date March 26, 2002

Page 1

### STS-110/8A

## Flight Readiness Review













Presenter	M. D. Erminger		
Date	March 26, 2002	Page	2

### Approach and General Description

S&MA held reviews in preparation for the STS-110/8A Flight Readiness Review on 6 and 22 March 2002 and is ready to proceed toward launch countdown.

#### **FRR Briefing Overview**

- Significant assessments discuss
- Special topics
  - NASA Safety Reporting System (NSRS) discuss
  - Space Shuttle Hazard Analysis discuss
  - Space Shuttle FMEA/CIL discuss
- Space Shuttle and Space Station Independent Assessments discuss
- Significant Open Work none
- CoFR Exceptions none
- Open Action Items none













Presenter	M. D. Erminger			
Date	March 26, 2002	Page	3	

### Significant Assessments

#### **Orbiter**

- Raytheon Transistor Intermetallic Growth
- STS-109 Freon Coolant Loop Degradation
- First Flight of OI-29 Software

#### **SSME**

Block II HPFTP Turbine Blade Shot Peen Process

#### **SRB**

STS-110 Hydraulic Pump Keenserts

#### ET/KSC

• STS-110/ET-114 Intertank Stringer Foam Damage

ADDITIONAL ASSESSED ITEMS ARE IN THE BACKUP CHARTS













Presenter	<sup>er</sup> M. D. Erminger			
Date	March 26, 2002	Page	4	

### Significant Assessments

#### **Space Station**

- SSRMS Wrist Roll Joint Anomaly
- Fluid QD Hydraulic Lockup
- 8A Berthing Loads
  - Procedure allows 30 seconds for Crew intervention to control hazard

#### **EVA**

Metal Oxide (METOX) Odor During Regeneration

ADDITIONAL ASSESSED ITEMS ARE IN THE BACKUP CHARTS













Presenter	M. D. Erminger		
Date	March 26, 2002	Page	5

### **OI-29 Flight Software – Safety Enhancements**

- Automated Alpha/Beta Management For TAL Aborts
  - Reduces Crew Workload During Time-critical Period and Increases Flight Safety by Reducing Probability of ET Debris Hitting the Orbiter
- RCS (Pressure, Volume, Temperature) PVT Sensor Change
  - Retains Crew/ground RCS Leak Detection Insight If MDM FA1 or FA2 is Lost
- Priority Rate Limiting Improvement
  - Improves Probability of Success for Single APU Landing by Reducing Potential For APU Pump Over-demand
- Change TAL Post-MECO ARCS 4 +X OMS Propellant Settling Burn
  - Decreases Probability Of ET Debris Hitting the Orbiter
- MPS LO2 Geyser Prevention
  - Automates MPS LO2 Safing Procedures for a Pad Abort or a Launch Scrub













riesentei	M. D. Erminge	er		
Date	March 26, 2002	Page	6	

## **Space Shuttle and Space Station Independent Assessments**

<u>Number</u>	<u>Title</u>	<u>Date</u>
JS-0038	Evaluation of RM2667-001 EEPROM Deficiencies Affecting Electrical Power System (EPS) Orbital Replacement Units (ORUs)	12/28/01
JS-1015	Adequacy of ISS Software Verification Plans and Schedules for Flight 8A	2/28/02
JS-0031	Thermal Evaluation of the S0 Truss in Support of the Functional Configuration Audit (FCA)	10/22/01
JA-1126	Revisit of the Analysis of the Commanding Processes for ISS	12/10/01
JA-1131	Evaluation of ISS Command Link Security Analysis	2/08/02
HS-1001	Mobile Transporter (MT) Element Level Physical Configuration Audit (PCA) Assessment	11/09/00
HS-1002	Integrated Truss Segment (ITS) S0 Functional Configuration Audit (FCA) Part 1 Assessment	11/29/00
HS-1004	Module to Truss Structure Attach System – Passive (MTSAS-P) Acceptance Review (AR) 2 Assessment	11/16/00
HS-1007	Incremental Configuration Audit (ICA) #4 Assessment for the Integrated Truss Segment (ITS) S0.	2/21/01
HS-1008	Integrated Truss Segment (ITS) S0 Functional Configuration Audit (FCA) Final Assessment.	3/16/01
HS-1010	Integrated Truss Segment (ITS) S0 Physical Configuration Audit (PCA) Assessment	3/26/01
HS-1011	Mobile Transporter (MT) Physical Configuration Audit (PCA) Assessment	4/10/01
JA-9109	Assessment of the Mobile Transporter (MT) During Functional Configuration Audit 2	6/30/01
JS-0029	Structural Evaluation of the S0 Truss Support of the FCA Audit	2/07/01
JS-1009	Investigation of Mobile Servicing System (MSS) Assembly and Capabilities	4/30/01













M. D. Erminger			er		
	Date	March 26, 2002	Page	7	

## **Space Shuttle and Space Station Independent Assessments**

<u>N u m b e r</u>	<u>Title</u>	<u>Date</u>
JS-1026	Evaluation of Mobile Transporter Thermal Behavior for the Rev. F Assembly Sequence	9/19/01
HS-0002	FCA/PCA Assessment for the Module to Truss Structure (MTS) Adjustable Struts	2/23/00
HS-0005	Mobile Transporter (MT) Element Level Functional Configuration Audit (FCA) Assessment	7/25/00
HS-0006	Functional Configuration Audit (FCA)/Physical Configuration Audit (PCA) Assessment for the Module to Truss Structure (MTS) Attach System	8/23/00
HS-0007	Functional Configuration Audit (FCA)/Physical Configuration Audit (PCA) Assessment for the Motorized Bolt Assembly (MBA)	8/23/00
HS-0008	Functional Configuration Audit (FCA)/Physical Configuration Audit (PCA) Assessment for the Trailing Umbilical System (TUS)	8/30/00
HS-0009	Functional Configuration Audit (FCA)/Physical Configuration Audit (PCA) Assessment for the Bolt Bus Controller (BBC)	9/01/00
HS-9013	Functional Configuration Audit (FCA)/Physical Configuration Audit (PCA) Assessment for the Mobile Transporter (MT) CI Level FCA/PCA Part 2	10/06/99
JS-0051	Evaluation of Extravehicular Mobility Unit Oxygen System Contamination Mitigation Plans	9/12/00
JS-9052	Readiness Review of ISS Berthing Operations for Flights 3A to 9A	11/05/99
HS-9009	Integrated Truss Segment (ITS) ŠO Secondary Structure Incremental Configuration Audit (ICA) Number Two	5/14/99
HS-9012	Incremental Configuration Audit (ICA) #3 Assessment for the Integrated Truss Segment S0	9/24/99
HS-0001	Functional Configuration Audit (FCA)/Physical Configuration Audit (PCA) Assessment for the Umbilical Mechanism Assembly (UMA), Active and Passive	2/01/00
JSC-98-004	PDR of the Oxygen Recharge Compressor Assembly System	11/03/97













M. D. Ermingei					
	Date	March 26, 2002	Page	8	

## **Space Shuttle and Space Station Independent Assessments**

<u>Number</u>	<u>Title</u>	<b>Disposition</b>
IA2-1002	Evaluation of MT Thermal Status from MT Component FCA	Closed
IA2-1003	MT: SSRMS Failure Modes	Closed
IA2-1004	Lack of Requirements for Berthing Corridor Definition	Closed
IA2-1005	MT: Flight Qual Requirements	Closed
IA2-1006	MT: Fit Checks Across Multiple Truss Segments Need to be Performed	Closed
IA2-1012	Review QD's Manifested on 8A and Assess Level of Fidelity of Fit Check S0/P1 and S0/S1	Closed
IA2-1013	Evaluate Impacts to SM Depress NCR Approval Given the Slip of 8A Software to 12A Timeframe	Closed
IA2-1015	Adequacy of External Control Zone (ECZ) Software Testing	Closed













Presenter	M. D. Erminger		
Date	March 26, 2002	Page	9

### **NSRS Summary**

There are no NASA Safety Reporting System reports open that are applicable to STS-110.

### Hazard Analysis Summary

There are no new Accepted Risk hazards identified for STS-110.

### **FMEA/CIL Summary**

There are no new Criticality 1 failure modes identified for STS-110.













Presenter M. D. Erminger Date 10 March 26, 2002

# STS-110/8A Readiness Statement

With the satisfactory completion of identified open work, Safety and Mission Assurance has no constraints to STS-110/8A. S&MA has no issues that constrain any of the mission success criteria.

<b>/S/</b> John Casper	<b>/S/</b> Shannon Bartell
SR&QA Director, JSC	Director, KSC Safety, Health and Independent Assessment
/S/ Amanda Goodson	<b>/S/</b> Bill Higgins
S&MA Director, MSFC	Chief, Shuttle S&MA, KSC
<b>/S/</b> Jerry Holsomback	<b>/S/</b> Hank Davis
ISS S&MA Manager	HEDS IA Director
/S/ Mark Erminger	<b>/S/</b> Mike Smiles
SS SR&QA Manager	S&MA Manager, SSC













M. D. Erminger

Date March 26, 2002

Page 11

### STS-110/8A

## Flight Readiness Review

**Backup Package** 













M. D. Erminger				
Date	March 26, 2002	Page	12	

### Raytheon Transistor Intermetallic Growth Risk Assessment

- No criticality 1R/2 or above applications contain the suspect LDC 7525
- At least one failure tolerant for all LCCs related to measurements impacted by LDC 7525
  - A total number of 27 unique LCCs are impacted
  - A total number of 95 measurements associated with an LCC
- No cases in which one failure of a LDC 7525 transistor can cause the loss of both the primary and secondary measurements processed by a DSC
- Analysis does not show a general end-of-life concern for 2N3019 transistors from any manufacturer or lot other than LDC 7525
- Criticality 1R/3 measurements are limited to:
  - 20 RCS (primary thruster); 4 Main Engine; 4 PCMMU; 3 MPS; 2 COAS; and 1ECLSS
- 4 RCS vernier fuel and oxidizer injector temperature measurements are Criticality
   2/2 generically, but only results in loss of reboost capability for STS-110
  - Loss of a vernier injector temperature measurement results in deselection of that thruster and subsequent loss of all vernier control
  - Vernier control is necessary for reboost, but not for primary mission objectives













Presenter	er M. D. Erminger		
Date	March 26, 2002	Page	13

### **Additional Assessments**

#### **Orbiter**

- First Flight of Modular Memory Unit (MMU) LRU Replacement
- First Flight of Block II Engine Cluster
- First Flight of Delayed TAL Implementation
- Payload Bay Door Strong Back Damage
- OMS Pod Attach Point #5 Anomaly
- WCS Check Valve Leak Check Failure
- MLG Wheel Bearing Test Anomaly
- OI-29 Telemetry/Command change incorporation into MCC software
- AMEC Power on Reset Anomaly
- STS-109 EMU Water Leak Issue
- STS-109 FES Accumulator/Hi-Load H2O Feedline B, Heater System 2 Failure













Presenter	M. D. Erminge	M. D. Erminger	
Date	March 26, 2002	Page	14

### **Additional Assessments**

#### **EVA**

- STS-109 EMU Battery Leakage
- EMU Radiation Monitor

#### <u>ET</u>

• LH2 Changes for SSME Block II Configuration

#### **SSME**

- First Flight of SSME Block II Cluster
- Block II HPFTP Turbine Exit Diffuser Inner Diameter Cracking

#### **RSRM**

• STS-110 Left Hand Aft Segment Re-Cast

#### **KSC SHIA**

• KSC OI-29 Telemetry/Command change incorporation into LCC software